1	Jordan L. Lurie (SBN 130013)						
2	Jordan.Lurie@capstonelawyers.com Tarek H. Zohdy (SBN 247775)						
3	Tarek.Zohdy@capstonelawyers.com Cody R. Padgett (SBN 275553)						
4	Cody.Padgett@capstonelawyers.com Karen L. Wallace (SBN 272309)						
5	Karen. Wallace@capstonelawyers.com Capstone Law APC						
6	1875 Century Park East, Suite 1000 Los Angeles, California 90067						
7	Telephone: (310) 556-4811 Facsimile: (310) 943-0396						
8	Attorneys for Plaintiffs						
9	Carlos Victorino and Adam Tavitian						
10	UNITED STATES DISTRICT COURT SOUTHERN DISTRICT OF CALIFORNIA						
11							
12	500 IIILIU DISI						
13	CARLOS VICTORINO and ADAM	Case No.: 3:16-CV-01617-GPC-JLB					
14	TAVITIAN, individually, and on behalf of a class of similarly situated individuals,	FIRST AMENDED CLASS ACTION COMPLAINT FOR:					
15	Plaintiffs,	(1) Violations of California's					
16	v.	Consumers Legal Remedies Act (2) Violations of Unfair Competition					
17	FCA US LLC, a Delaware limited	Law (3) Breach of Implied Warranty					
18	liability company,	pursuant to Song-Beverly Consumer Warranty Act					
19	Defendant.	(4) Breach of Implied Warranty pursuant to the Magnuson-Moss					
20		Warranty Act (5) Unjust Enrichment					
21		DEMAND FOR JURY TRIAL					
22							
23							
24							
25							
26							
27							
28							

3 4

5

6

7

8 9

10

11

12

13

14

15

16

17

18

19

20

21

22

23 24

25

26

27 28

1. Plaintiffs Carlos Victorino and Adam Tavitian ("Plaintiffs") bring this action for themselves and on behalf of all persons in the United States who purchased or leased any Dodge Dart vehicles¹ equipped with a Fiat C635 manual transmission ("Class Vehicles") designed, manufactured, marketed, distributed, sold, warranted and serviced by FCA US LLC, a Delaware limited liability company ("FCA" or "Defendant").

- The hydraulic clutch system ("Clutch System") in the Class Vehicles is defective in that the clutch pedal loses pressure, sticks to the floor, and fails to engage/disengage gears. As a result, the Class Vehicles exhibit stalling, failure to accelerate, and premature failure of the Clutch System's components, including the clutch master cylinder and reservoir hose, clutch slave cylinder and release bearing, clutch disc, pressure plate, and flywheel (the "Clutch Defect").
- 3. Since 2012, in an effort to address owner complaints regarding the Clutch Defect, FCA has issued Technical Service Bulletins ("TSBs"), customer satisfaction campaigns ("CSCs"), and STAR cases, as detailed below. However, these efforts have been entirely inadequate in remedying the Clutch Defect. In fact, rather than redesigning the defective components, FCA has perpetuated the Clutch Defect by failing to replace all defective components during repairs. Further, Class Vehicle owners experiencing the Clutch Defect must pay for the temporary repairs, often totaling over \$2,000.
- Additionally, FCA refuses to pay for any repair costs associated with the collateral damage caused by the Clutch Defect, including the recurring replacement of the clutch slave cylinder and release bearing, clutch disc and

¹ On information and belief, these vehicles include 2013-2016 Dodge Darts.

- 5. The Class Vehicles are equipped with a hydraulic clutch system that includes the clutch pedal, the Clutch Master Cylinder, the Clutch Slave Cylinder, a fluid reservoir, a reservoir hose, interconnecting hydraulic line, and a clutch assembly. The clutch pedal is connected to the Clutch Master Cylinder via a push-rod. The clutch assembly includes the clutch disk, the pressure plate, and the flywheel. When the driver depresses the clutch pedal, a piston inside the Clutch Master Cylinder displaces fluid. The pressurized fluid transmits force through a tube connecting the Clutch Master Cylinder to the Clutch Slave Cylinder. In turn, a piston inside the Clutch Slave Cylinder pushes against a release bearing (also called a "throw-out" bearing or "TO" bearing) that disengages the engine from the transmission. The Concentric Slave Cylinder used in the Class Vehicles integrates the release bearing as a single Clutch System component. When the driver releases the clutch pedal, the pressure is released, the clutch assembly should engage the gears smoothly.
- 6. Overall, these components work together to engage and release the engine from the transmission in a smooth and predictable manner. If any components are damaged, the Clutch System can fail to operate correctly, which prevents the gears from engaging or disengaging properly. Such failure can cause additional damage to the Clutch System, including causing the clutch disc to overheat, and prevent the gears from engaging, preventing the driver from shifting and accelerating or causing the vehicle to stall.
- 7. The Clutch Defect is caused by contaminated hydraulic fluid. Specifically, the clutch reservoir hose in the Clutch System degrades, releasing plasticizer and fibers into the hydraulic fluid that bathes the Clutch System components. This contamination causes the seals in the Clutch Master Cylinder and Clutch Slave Cylinder to swell and fail.

- 8. When fluid in a hydraulic system becomes contaminated, all of the components that have been exposed to the contaminated fluid must be replaced. Any steel tubing must also be thoroughly cleaned with brake cleaner and blown out until dry to ensure that none of the contaminants remain. In the case of the Class Vehicles, fibers and plasticizer can and do migrate throughout the Clutch System and cause other components to fail. The degradation of the reservoir hose and concomitant release of debris contaminates the entire Clutch System, including the internal and external seals in the Clutch Master Cylinder and Clutch Slave Cylinder.
- 9. Since 2012, if not earlier, FCA has been aware of the Clutch Defect. As a result of its findings, and in response the Clutch Defect, FCA issued a customer service program, the "Clutch Pedal Operation X62 Extended Warranty," and accompanying technical service bulletin ("TSB") requiring technicians to replace the reservoir hose and clutch master cylinder. These repairs omit the Clutch Slave Cylinder, even though it is subject to the same contaminated fluid that necessitates replacement of the Master Cylinder.
- 10. FCA has admitted that the reservoir hose leaches plasticizer, which causes it to degrade and release fibers, to contaminate the hydraulic fluid, and to damage the Clutch Master Cylinder's seals. Per FCA, this contamination necessitates replacement of both the clutch master cylinder and the reservoir hose. However, FCA's TSB 06-001-16 REV.A, published August 27, 2016, which describes the X62 extended warranty and repair procedure, fails to provide for replacement of the Clutch Slave Cylinder, even though it is bathed in the same hydraulic fluid and subject to the same contamination that necessitates replacement of the clutch Master Cylinder.
- 11. The X62 Extended Warranty should have included replacement of the slave cylinder and a thorough cleaning of the metal tubing to remove any

contamination.

- 12. It is relatively simple and inexpensive to replace the clutch Master Cylinder and reservoir hose pursuant to FCA's repair procedures. Replacing the Clutch Slave Cylinder, however, requires technicians to separate the engine from the transmission, which is both expensive and time-consuming. FCA's X62 repair procedure has remained limited to the clutch master cylinder and reservoir hose through numerous revisions and updates, even though the Clutch Slave Cylinder should be replaced to complete the repair required by the contaminated fluid and to resolve the Clutch Defect.
- 13. In addition, there is defect in the Clutch Slave Cylinder which exacerbates Clutch System failures. Unlike other manufacturers who make slave cylinders as a single, solid cast aluminum component, FCA designed its Clutch Slave Cylinder as an assembly composed of an aluminum body with a clipped-on plastic base. Whereas the competing solid aluminum slave cylinder integrates a rigid base—with the cylinder bored directly into the cast aluminum—FCA's two-piece design destabilizes the cylinder at its the base, which can result in unintended lateral movement and cause the piston inside the cylinder to become jammed.
- 14. On information and belief, the Clutch Defect also causes premature wear to Clutch System components, which similarly requires replacement of the clutch slave cylinder/release bearing, the clutch master cylinder, the reservoir hose, and the clutch assembly (including the disc and pressure plate).
- 15. On information and belief, the Class Vehicles equipped with the Fiat C635 transmission have the same or substantially identical transmissions, and the Clutch Defect is the same for all Class Vehicles.
- 16. The Clutch Defect causes unsafe conditions, including the inability to shift gears or operate the clutch pedal, thereby preventing drivers of the Class

1	Vehicles from changing speed, often while in traffic. These conditions are					
2	hazardous because they severely affect the driver's ability to control the					
3	vehicle's acceleration and deceleration. For example, the Clutch Defect makes it					
4	difficult for drivers to maintain appropriate speeds; Plaintiffs and Class					
5	Members' clutch pedals fail, which prevents them from accelerating safely when					
6	they attempt to change lanes and/or merge onto the highway. ² The Clutch Defection					
7	has also prevented Plaintiffs and Class Members from safely stopping or parking					
8	their vehicles because they cannot downshift to decelerate as they brake.					
9	17. Defendant knew or should have known that the Class Vehicles and					
10	the Clutch System has had a design defect that adversely affects the drivability of					
11	the Class Vehicles and causes safety hazards, in part, because the same concerns					
12	were expressed regarding the 2011-2012 models year Dodge Journey that had a					
13	substantially similar manual transmission as the Class Vehicles'.					
14	18. On information and belief, Defendant's corporate officers, directors,					
15	or managers knew about the Clutch Defect and failed to disclose it to Plaintiffs					
16	and Class Members, at the time of sale, lease, repair, and thereafter.					
17	19. In fact, on or around January 20, 2012, Chrysler issued TSB "06-					
18	001-12" for the 2011-2012 Dodge Journey vehicles equipped with the Fiat C635					
19						
20	² See, for example, this 2014 Dart owner's complaint to the National					
21	Highway Traffic Safety Administration ("NHTSA"): (2014 Dodge Dart 4/9/2015) PURCHASED A 2014 DODGE DART USED WITH A 6 SPEED.					
22	THIS INCIDENT HAPPENED JUST THREE WEEKS AFTER I PURCHASED IT. I NOTICED IT STARTED TO SLIP AND WHILE DRIVING DOWN THE					
23	HIGHWAY I HEARD A NOISE, CAR LOST POWER AND SMOKE STARTED POURING OUT FROM UNDER THE HOOD. I HAD IT TOWED TO THE DEAL ERSHIP WHERE I WAS INFORMED THAT SOMETHING					
24	TO THE DEALERSHIP WHERE I WAS INFORMED THAT SOMETHING FAILED IN THE CLUTCH, BLOWING A HOLE THROUGH THE					
25	TRANSMISSION. THIS ALL HAPPENED WITHIN A MINUTE OR SO WHILE DRIVING AT HIGHWAY SPEEDS. (Safercar.gov, Search for Safety					
26	Problems (May 19, 2016), http://www-odi.nhtsa.dot.gov/owners/Search SafetyIssues).					

27

³ The same bulletin is referred to as "2011 Dodge Journey Power Train Service Bulletin 329136" and "2012 Dodge Journey Power Train Service Bulletin 329136."

transmission. The Service Bulletin stated that the clutch pedal was inoperative in some vehicles.

- 20. Further, in or around November 2012, FCA issued TSB 10051770-2112 informing dealers that certain 2013 Dodge Dart vehicles were equipped with defective clutch slave cylinders that could cause a hydraulic fluid leak, which leads to a pressure loss in the clutch system and failure of the clutch pedal. FCA instructed its dealers to replace the clutch slave cylinder in the affected vehicles.
- 21. Then, on or around August 15, 2014, FCA released STAR case number S1406000001 to its dealers addressing an issue in Dodge Dart vehicles equipped with the Fiat C635 transmission where the "Clutch Pedal Does Not Return (Remains on the Floor) After Depressing the Pedal." FCA instructed its dealers to inspect the clutch pedal and replace the clutch master cylinder and reservoir hose, if necessary.
- 22. Additionally, in or around January 2016, FCA extended the clutch master cylinder and reservoir hose warranty period because 2013-2015 Dodge Dart vehicles were exhibiting a "loss of clutch pedal operation including limited pedal travel and limited clutch disengagement." FCA also provided reimbursement for Dodge Dart owners who experienced these clutch issues and previously paid for clutch master cylinder repairs. On information and belief, the campaign neither fixed the Clutch Defect nor actually reimbursed all owners affected by the Clutch Defect for repairs performed on the clutch master cylinder and reservoir hose.
- 23. Because FCA will not notify Class Members that the Clutch System is defective, Plaintiffs and Class Members (as well as members of the general public) remain subject to dangerous driving conditions that often occur without warning.

- 24. The alleged Clutch Defect is inherent in each Dodge Dart's Fiat C635 transmission Clutch System and was present in each Dodge Dart Clutch System at the time of sale.
- 25. FCA knew about and concealed the Clutch Defect present in every Class Vehicle, along with the attendant dangerous safety and driveability problems, from Plaintiffs and Class Members, at the time of sale, lease, and repair and thereafter. In fact, instead of repairing the defects in the Clutch System, FCA either refused to acknowledge their existence, or performed repairs that simply masked them.
- 26. If Plaintiffs and Class Members had known about these defects at the time of sale or lease, Plaintiffs and Class Members would not have purchased or leased the Class Vehicles or would have paid less for them.
- 27. As a result of their reliance on Defendant's omissions, owners and/or lessees of the Class Vehicles suffered an ascertainable loss of money, property, and/or value of their Class Vehicles, including out of pocket costs related to repairs to the Clutch System. Additionally, as a result of the Clutch Defect, Plaintiffs and Class Members were harmed and suffered actual damages in that the Class Vehicles' clutch components are substantially certain to fail before their expected useful life has run.

THE PARTIES

Plaintiff Carlos Victorino

- 28. Plaintiff Carlos Victorino is a California citizen who resides in Chula Vista, California.
- 29. On or about March 22, 2014, Mr. Victorino purchased a new 2014 Dodge Dart from San Diego Chrysler Dodge Jeep Ram ("San Diego Dodge"), an authorized FCA dealer in San Diego County. Mr. Victorino's vehicle was equipped with a Fiat C635 transmission.

- 30. Mr. Victorino purchased his vehicle primarily for personal, family, or household use. FCA manufactured, sold, distributed, advertised, marketed, and warranted the vehicle.
- 31. Passenger safety and reliability were factors in Mr. Victorino's decision to purchase his vehicle. Prior to purchasing his vehicle, Mr. Victorino spent time researching the Dodge Dart on Dodge's corporate website. Based on his research, Mr. Victorino believed that the Dodge Dart would be a safe and reliable vehicle. Mr. Victorino also test drove his vehicle with a dealership salesperson prior to purchase.
- 32. Had FCA disclosed its knowledge of the Clutch Defect before he purchased his vehicle, Mr. Victorino would have seen such disclosures and been aware of them. Indeed, FCA's omissions were material to Mr. Victorino. Like all members of the Class, Mr. Victorino would not have purchased his Class Vehicle, or would have paid less for it, had he known of the Clutch Defect.
- 33. Since purchasing his Dodge Dart, Mr. Victorino experienced symptoms of the Clutch Defect, including the clutch failing to engage gears and stalling. From the first day he owned the vehicle, it would "stall out" nearly every day. In the beginning, he thought it was just him getting used to the new vehicle. But it kept continuing and after the vehicle would stall, it would not turn back on.
- 34. By January 2016, with only 34,300 or so miles on the odometer, the Clutch Defect had rendered the vehicle undriveable. On or about January 10, 2016, Victorino noticed that the gears were not properly 'catching' when attempting to shift. The vehicle was bogging down and failing to accelerate as a result.
- 35. On or around January 13, 2016, with approximately 34,351 miles on the odometer, Mr. Victorino brought his vehicle to San Diego Dodge

- 36. Mr. Victorino contacted FCA's Customer Assistance Center seeking assistance, telling them that his clutch had failed, and that this is a known issue whereby repairs are ineffective at permanently fixing the problem. FCA told Mr. Victorino that his clutch kit repairs would not be covered because the damage was due to normal wear and tear. Mr. Victorino also applied for reimbursement under FCA's X62 Extended Warranty Program, but FCA denied coverage, taking the position that his clutch problems were his fault.
- 37. Since the January 2016 repair, Mr. Victorino's clutch pedal has felt soft and sometimes drops to the floor. For example, in May 2017, the clutch pedal dropped and became stuck half way down. When he pressed the pedal, it would not come back up. Mr. Victorino had to pop the clutch pedal up with his feet.
- 38. At all times, Mr. Victorino, like all Class Members, has driven his vehicle in a foreseeable manner and in the manner in which it was intended to be used.

Plaintiff Adam Tavitian

- 39. Plaintiff Adam Tavitian is a California citizen who resides in North Hollywood, California.
- 40. On or around November 17, 2012, Mr. Tavitian purchased a new 2013 Dodge Dart from Stewart Chrysler Dodge Jeep Ram, an authorized FCA

dealer in San Mateo County ("Stewart Chrysler"). Mr. Tavitian's vehicle was equipped with a Fiat C635 Manual Transmission.

- 41. Mr. Tavitian purchased his vehicle primarily for personal, family, or household use. FCA manufactured, sold, distributed, advertised, marketed, and warranted the vehicle.
- 42. Passenger safety and reliability were factors in Mr. Tavitian's decision to purchase his vehicle. Prior to purchasing his vehicle, Mr. Tavitian spent time researching the Dodge Dart on Dodge's corporate website. Based on his research, Mr. Tavitian believed that the Dodge Dart would be a safe and reliable vehicle. Mr. Tavitian also test drove his vehicle with a dealership salesperson prior to purchase.
- 43. Had FCA disclosed its knowledge of the Clutch Defect before he purchased his vehicle, Mr. Tavitian would have seen such disclosures and been aware of them. Indeed, FCA's omissions were material to Mr. Tavitian. Like all members of the Class, Mr. Tavitian would not have purchased his Class Vehicle, or would have paid less for it, had he known of the Clutch Defect.
- 44. Within the first six months of ownership, the clutch pedal did not work properly. For example, the clutch pedal would feel "heavy." When he would lift his foot from the clutch pedal, the pedal would lag, then release and hit his foot on the way up.
- 45. In July 2014, when he was driving on the start of a steep incline on Interstate 5 called the "Grapevine", Tavitian's clutch stuck to the floor and he was forced to pull it up after each shift for over 50 miles.
- 46. On July 7, 2014, Mr. Tavitian took his vehicle to Rydell Chrysler, complaining that the clutch pedal installed in his Dodge Dart would stick in the depressed position and fail to shift gears. As was his habit with all dealership visits, to make sure the dealership knew the correct mileage on his vehicle, Mr.

Tavitian provided the dealership with proof of the mileage on his odometer, as his improved instrument panel cluster's display was not synched with the vehicle's odometer. The service technician inspected the vehicle and determined that the clutch master cylinder was leaking and subsequently replaced it at a cost of \$298.33 to Mr. Tavitian. In May 2016, Mr. Tavitian requested reimbursement from FCA for the repair costs incurred in replacing the clutch master cylinder in response to FCA's customer service campaign providing for such reimbursement. However, Mr. Tavitian's claim was denied.

- 47. Despite requesting reimbursement for the clutch master cylinder replacement per FCA's customer service campaign in early 2016, receiving a letter from FCA informing him that his Class Vehicle was included in its CSP, which extended the warranty of the clutch master cylinder and reservoir hose and provided reimbursement to owners of the affected vehicles who previously replaced the cylinder and/or hose, FCA denied Mr. Tavitian's claim for reimbursement.
- 48. Around July 9, 2016, Tavitian's vehicle clutch failed while driving to Palm Springs. It stuck to the floor, and he was not able to pull it back up. The car was towed to Glendale Dodge Chrysler Jeep. During the visit, FCA conducted a legal inspection. The dealer replaced the clutch master cylinder and the reservoir hose. However, despite these repairs—the very repairs FCA provided under its X62 Extended Warranty program—the clutch pedal was still stuck down. After further inspection, it was determined the slave cylinder's throw out bearing was coming apart and leaking. Further, the clutch was worn out with signs of overheating. Mr. Tavitian was told that the whole clutch system would have to be replaced at a cost of approximately \$1,700.
- 49. Mr. Tavitian declined repairs at the dealership. Instead, he had his vehicle repaired in October 2016 at J&E Auto Services, Inc., where a new clutch

57.	Jurisdiction	is proper in	this Court pursuant to	28 U.S.C.	§ 1332(d)
-----	--------------	--------------	------------------------	-----------	-----------

VENUE

- 58. FCA, through its business of distributing, selling, and leasing the Class Vehicles, has established sufficient contacts in this district such that personal jurisdiction is appropriate. Defendant is deemed to reside in this district pursuant to 28 U.S.C. § 1391(a).
- 59. In addition, a substantial part of the events or omissions giving rise to these claims and a substantial part of the property that is the subject of this action are in this district. In addition, Plaintiff Carlos Victorino's Declaration, as required under California Civil Code section 1780(d) but not pursuant to *Erie* and federal procedural rules, reflects that a substantial part of the events or omissions giving rise to the claims alleged herein occurred, or a substantial part of property that is the subject of this action, is situated in San Diego County, California. It is attached as Exhibit 1.
 - 60. Venue is proper in this Court pursuant to 28 U.S.C. § 1391(a).

FACTUAL ALLEGATIONS

- 61. Since 2012, FCA has designed, manufactured, distributed, sold, and leased the Class Vehicles. FCA has sold, directly or indirectly, through dealers and other retail outlets, thousands of Class Vehicles equipped with the Fiat C635 manual transmission and Clutch System in California and nationwide.
- 62. As discussed above, the Clutch System contains a design defect that causes, among other problems, the clutch pedal to lose pressure, stick to the floor, and fail to engage/disengage gears. As a result, the vehicles equipped with the Clutch System experience stalling, gears failing to engage properly, and premature failure of the transmission's components, including the clutch master cylinder and reservoir hose, clutch slave cylinder/release bearing, clutch disc, pressure plate, and flywheel (the "Clutch Defect").

- 63. As discussed above, the Clutch Defect is caused by contamination in the Clutch System's hydraulic fluid which occurs when the reservoir hose degrades, releasing plasticizer and fibers into the hydraulic fluid that bathes other Clutch System components. Among other problems, this contamination causes the internal and external seals in the Clutch Master Cylinder and Clutch Slave Cylinder to swell and fail.
- 64. Repairing damage caused by contaminated hydraulic fluid requires the replacement of all the components that have been exposed to the contamination. In addition, the Clutch System's steel tubing must be thoroughly cleaned with brake cleaner and dried to ensure that all contaminants have been eliminated. In the case of the Clutch System components at issue, fibers and plasticizer migrate throughout and cause other components to fail.
- 65. As discussed above, FCA has been aware of the Clutch Defect since at least 2012 and issued the X62 customer service program where drivers "experience a reduction in clutch pedal stroke." The accompanying TSB only requires technicians to replace the clutch master cylinder and reservoir hose, which fails to address contamination of the Clutch Slave Cylinder, among other components.
- 66. FCA has admitted that the reservoir hose leaches plasticizer, which contaminates the hydraulic fluid and damages the Clutch Master Cylinder's seals. FCA has also admitted that repairing the damage this contamination causes requires replacing both the clutch master cylinder and the reservoir hose. However, FCA's August 27, 2016, TSB 06-001-16 REV.A, which describes the X62 extended warranty and repair, omits other components subject to contamination, including the Clutch Slave Cylinder.
- 67. The Clutch Defect is exacerbated by the poor design of the Clutch Slave Cylinder

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

2526

27

28

68. The Clutch Defect causes dangerous conditions. When the clutch pedal fails, drivers of the Class Vehicles' cannot shift gears, thereby preventing them from changing speed as necessary in traffic. The Clutch Defect creates a safety hazard because it severely affects the driver's ability to accelerate or decelerate as traffic and road conditions change. For instance, the Clutch Defect can prevent drivers from maintaining appropriate speeds in order to change lanes or merge into traffic safely.

69. Hundreds of purchasers and lessees of the Class Vehicles have experienced problems with the Clutch System. Complaints filed by consumers with the National Highway Traffic Safety Administration ("NHTSA") demonstrate that the defect is widespread and dangerous and that it manifests without warning. The complaints also indicate Defendant's awareness of the Clutch Defect and the potentially dangerous driving conditions it creates. The following are some safety complaints relating to the Clutch Defect (spelling and grammar mistakes remain as found in the original) (Safercar.gov, *Search for Safety Issues* (May 25, 2016), http://www-odi.nhtsa.dot.gov/owners/SearchSafetyIssues/):

2013 Dodge Dart:

a. 2/2/2013 THIS VEHICLE SHIFTS SO BAD AND THAT CARS I'VE DRIVEN THAT WERE 5 - 10 YEARS OLDER SHIFTED BETTER THAN THIS . IT DOWNSHIFTS WHILE BRAKING AND SOMETIME IT IS A VERY JERKY DOWNSHIFT .ALSO IT SLAMS/JOLTS INTO FIRST GEAR WHILE ROLLING AT ABOUT 3-5 MILES PER HOUR ONCE THE PEDAL IS PUSHED. IT ALSO IS THE WORST AT CHANGING GEARS DURING STOP AND GO DRIVING BECAUSE IT IS SO JERKY AND BOUNCY AFTER BRAKING THEN ACCELERATING AND I DON'T SEE WHY A CAR THAT IS BRAND NEW SHOULD DO THIS. AFTER TAKING IT TO THE DEALER AND HAVING THEM TELL ME TO BRAKE IT IN FIRST, I HAVE DONE SO AND HAVE 700+ **HAVE** ON THEM MILES IT AND HAD **PERFORM** TRANSMISSION FLASH UPDATES WITH NO EFFECT ON THE CAN'T SHIFTING PROBLEMS. Ι SEE HOW TRANSMISSION(AND ALL PARTS THAT WORK TOGETHER WITH IT)WILL LAST WITH THESE SORT OF THINGS

HAPPENING. ALSO IT BOGS OUT BECAUSE IT WON'T DOWNSHIFT WHEN IT SHOULD AND STAYS AT ABOUT 1300-1400 RPM'S WHEN IT SHOULD BE ABOUT 4-5000 RPM'S HIGHER. I'VE DRIVEN NEW CARS AND THE DODGE DART 2013 SE 2.0 LITER MODEL SEEMS LIKE IT WASN'T READY YET FOR THE ROAD. THE ACCELERATION IS VERY BOUNCY TOO WHEN IT SHOULD BE A STEADY ACCELERATION. *TR

- b. 3/25/2013 WHEN DRIVING DOWN THE HIGHWAY, I ATTEMPTED TO DOWNSHIFT TO CHANGE LANES. THE CLUTCH BASICALLY POPPED AND WENT TO THE FLOOR. I THEN HAD TO SWERVE IN TRAFFIC IN ORDER TO GET OFF THE HIGHWAY. I HAVE A 2013 DART SXT WITH THE 1.4L MULTIAIR ENGINE AND THE 6 SPEED TRANSMISSION. AFTER LOOKING AROUND ON THERE WEB, THIS IS APPARENTLY NOT AN ISOLATED INCIDENT AND MAY ACTUALLY BE A KNOWN ISSUE WITH THE VEHICLES. CHRYSLER NEEDS TO NOT ONLY FIX THIS PROBLEM, BUT IT SHOULD BE RECALLED AS IT CAN HAPPEN AT ANY TIME. I HAVE FOUND THAT SOME VEHICLES HAVE THIS HAPPEN IN AS LITTLE AS THE FIRST FEW DAYS OF OWNERSHIP OR AS IN MY CASE, AFTER A FEW THOUSAND MILES. IT IS DANGEROUS. I WOULD PUT IN THE VIN, BUT THE CAR IS CURRENTLY AT THE DEALERSHIP AS THIS HAPPENED TODAY. THANK YOU. *TR
- c. 8/8/2013 ON THREE SEPARATE OCCASIONS WHEN I AM IN TRAFFIC AND HAVE TO DO A LOT OF START/STOP THE CAR STALLS, WILL NOT GO INTO GEAR AND START SMOKING. IT SMELLS AS IF THE CLUTCH IS BURNING AND THE CAR WILL NOT GO INTO GEAR. I HAVE TO PULL OVER FOR ABOUT 30MIN TO AN HOUR TO STOP THIS FROM CONTINUING. THIS IS A BRAND NEW CAR AND I HAVE TAKEN IT TO THE DEALER AND THEY OF COURSE CANT DUPLICATE THE PROBLEM AND THE TECH IS TELLING ME THE CLUTCH IS OVERHEATING BECAUSE OF USER ERROR. I HAVE BEEN DRIVING A STICK SHIFT FOR ABOUT 15 YEARS AND HAVE NEVER HAD ANY PROBLEMS WITH MY OTHER STICK SHIFTS LIKE THIS ONE. EVERYONE AROUND ME CAN SEE THE CAR SMOKING AND MY DAUGHTER IS SCARED TO DEATH TO GET BACK IN THE CAR BECAUSE SHE HAS EXPERIENCED THIS TWICE NOW AND SHE IS ONLY 4 YEARS OLD SHE THINK THE CAR IS GOING TO CATCH ON FIRE. I SHOULD NOT HAVE TO PULL OVER FOR AN HOUR EVERYTIME I AM IN TRAFFIC. I LIVE IN A CITY WHERE THAT IS NOT PREVENTABLE. THERE HAS GOT TO BE SOMETHING THAT CAN BE DONE ABOUT THIS. *TR
- d. 8/20/2013 1. CLUTCH STARTED TO LOSE RESISTANCE COUPLE TIMES A MONTH IN TWO LAST MONTHS. NOW ALMOST EVERY DAY AFTER LONG TIME NOT USING IT. IT FREELY GOING DOWN, SOMETIMES STUCK IN THE HALF WAY OUT AND HAVE TO BE PULLED UP. 2. BRAKES STARTED LOSE RESISTANCE RECENTLY ALSO AFTER LONG TIME NOT TO BE USED (1 OR MORE HOURS)

26

27

28

SPECIALLY IN THE MORNING. IT FREELY GOING DOWN HALF WAY PRODUCING AIR BLOW SOUND. AFTER A FEW TIMES PUSHING PEDAL DOWN AIR BLOW STOPS AND RESISTANCE GETS OK. BEHIND OF BRAKE PEDAL IT FEELS SOME KING OF LIQUID. 3. ACCELERATION AT HIGH SPEED TAKES LONGER TIME THEN IT WAS BEFORE AND REQUIRES TO SWITCH TO LOWER GEAR. (TURBO PROBLEM?) 4. MPG DECREASED. ON THE SAME WAY TO AND BACK TO WORK USUALLY IT WAS 32-33 MPG. NOW IT GETS 28-29 TODAY BROUGHT CAR TO DEALER. AFTER A WHOLE DAY OF INSPECTION NOTHING WRONG WAS FOUND. *TR

- e. 9/8/2013 WHEN I GO TO SHIFT FROM 1ST TO 2ND GEAR THE CLUTCH PEDAL STAYS DEPRESSED, THIS KEEPS THE CAR IN NEUTRAL AND LEAVING IT UNABLE TO DELIVER POWER TO MANEUVER.
- f. 9/12/2013 CLUTCH PEDAL DOES NOT ALWAYS COME ALL THE WAY BACK UP. I HAVE TO PULL IT UP WITH MY FOOT. I CAN TELL IT DOES NOT HAVE THE CLUTCH ENGAGED TO BURN IT OUT. JUST A IRRITATING THING TO HAVE TO DO ON A BRAND NEW CAR. TOOK IT TO THE DEALERSHIP FOR ANOTHER ISSUE AND HAD THEM CHECK IT. THEY COULD NOT GET IT TO STICK. AND SINCE CHRYSLERS SYSTEM WAS DOWN THEY DIDN'T KNOW WHAT TO LOOK AT. THIS AND RANDOM TIMES. THIS **MORNING HAPPENS** HAPPENED. WHEN I WENT TO PUSH THE CLUTCH DOWN I COULD TELL THERE WAS NO RESISTANCE FOR A FEW INCHES. WHEN I RELEASED THE CLUTCH IT ONLY CAME PART WAY UP AGAIN. BIGGEST FRUSTRATION IS THE TECH'S CAN NOT PROBLEM SOLVE ANYTHING WITH OUT A COMPUTER TELLING THEM WHAT TO DO. I MADE A FEW SUGGESTIONS ON WHAT TO CHECK BUT THEY HAD NOT CLUE. SINCE THIS IS THE FIRST YEAR FOR THIS CAR I DO EXPECT BUGS IN THE SYSTEM. HOWEVER THEY SHOULD BE PREPARED TO PROBLEM SOLVE THIS PROBLEMS. I SHOULD NOT HAVE TO MAKE SUGGESTIONS OR PROBLEM SOLVE IT MYSELF. *TR
- g. 10/24/2013 PRESSED IN CLUTCH PEDAL TO START VEHICLE. AFTER CAR STARTED, TRIED TO TAKE CAR OUT OF GEAR BUT IT WOULDN'T BUDGE. ALSO, THE CLUTCH PEDDLE WOULD NOT RELEASE, AS IT WAS STUCK TO THE FULLY PRESSED POSITION. CAR BEGAN TO ROLL AS IF IT STARTED TO DISENGAGE BUT THE PEDDLE WAS STILL COMPLETELY PRESSED IN. I IMMEDIATELY TURNED THE CAR OFF. I HAD TO PULL THE CLUTCH PEDDLE UP BY HAND TO GET IT TO DISENGAGE. CALLED DEALER SERVICE, SAID THEY COULDN'T RESOLVE THE ISSUE IF THEY COULDN'T DUPLICATE THE PROBLEM. I'VE NOTICED MANY PEOPLE WITH THE SAME ISSUE. CHRYSLER NEEDS TO ISSUE A RECALL ON THIS. *TR
- h. 1/2/2014 ANOTHER TIME CLUTCH WOULD NOT COME UP AND STAYED TO THE FLOOR, CLUTCH FLUID LEAKED

24

25

26

27

28

1

- 3/12/2014 AFTER SEVERAL HOURS OF STAYING PARKED WITH TRANSMISSION IN GEAR (1ST), VEHICLE WOULD NOT DISENGAGE GEARBOX ON STÀRTÚP. CLUTCH LOST ALL PRESSURE AND THE VEHICLE REQUIRED EXCESSIVE USE OF FORCE TO DISLODGE GEAR SHIFTER. VEHICLE WAS STARTED (CLUTCH DISENGAGED AND IN NEUTRAL) AND FORWARD. BEGAN DRIVE VEHICLE TO CLUTCH/TRANSMISSION REMAINED IN CONTACT WITH ENGINE CAUSING THE VEHICLE TO CONTINUE MOVING EVEN FORWARD WHILE IN NEUTRAL. TRANSMISSION/CLUTCH WOULDN'T REENGAGE WITHOUT EXCESSIVE FORCE. *TR
- 3/24/2014 BRAND NEW 2013 DODGE DART, SIX SPEED TRANSMISSION. MANUAL **SMELLING** BEGAN SMOKING WHEN TEACHING MY SON HOW TO START ON A HILL. SMOKE WAS COMING FROM FRONT RIGHT SIDE OF TRANSMISSION. SMELLED LIKE A BURNING CLUTCH. THIS OCCURRED AFTER A SHORT PERIOD OF TIME ON THE HILL THAN FIVE MINUTES). TOOK CAR BACK TO DEALERSHIP TODAY (3-24-14), AND WAS TOLD THERE IS A STICKER ON THE TRANSMISSION THAT BURNS (IT WAS REMOVED TODAY, AND HAS BEEN REMOVED ON OTHER THEY HAVE WORKED ON FOR DARTS THE PROBLEM), AND THE SMELL AND SMOKE WERE ALSO COMING FROM THE CLUTCH. THEY TEST DROVE THE CAR OVER SOME HILLS NEAR THE DEALERSHIP AND WERE ABLE TO REPRODUCE THE SAME SMELL, BUT SAID IT IS LIKELY CAUSED BY THE NEW CLUTCH AND SHOULD BE DRIVEN 1500-2000 MILES BEFORE BEING CONCERNED ABOUT THIS ISSUE. I HAVE NEVER EXPERIENCED CLUTCH BURNING LIKE THIS, ESPECIALLY AFTER SUCH A SHORT PERIOD OF TIME ON THE HILL, AND I'VE DRIVEN MANY MANUAL CARS/TRUCKS OVER MANY YEARS. *TR
- k. 4/17/2014 TL* THE CONTACT OWNS A 2013 DODGE DART. THE CONTACT STATED THAT WHILE TRAVELING VARIOUS SPEEDS, THE VEHICLE FAILED TO RESPOND TO DECELERATION ATTEMPTS. THE VEHICLE WAS NOT DIAGNOSED OR REPAIRED. THE MANUFACTURER WAS NOT CONTACTED ABOUT THE FAILURE. THE FAILURE MILEAGE WAS 3,500.
- 1. 5/7/2014 I WENT OUT IN THE MORNING TO START THE CAR AND IT WOULD NOT GO INTO REVERSE. THE GEAR STICK FELT STUCK AND I HAD TO HAVE MY HUSBAND COME OUT AND PUT THE CAR INTO NEUTRAL AND ROLL THE CAR BACK SO WE COULD START IT IN FIRST. THIS HAPPENED AGAIN ONE MONTH LATER, ONLY THE CAR WOULD NOT EVEN GO INTO FIRST GEAR. WE HAD IT TOWED TO DEALER AND WERE TOLD WE HAD TO PAY FOR A NEW CLUTCH-IT WAS BURNED OUT. BURNED OUT AT 18,000 MILES. WE PAID FOR A NEW CLUTCH, AND NOW 4MTHS LATER, THE CAR IS DOING THE SAME THING. PROBLEM GOING INTO REVERSE. DEALER CAN FIND NOTHING WRONG WITH IT-I AM

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

- m. 5/12/2014 WENT TO START MY CAR IN THE MORNING PUSHED THE CLUTCH TO THE FLOOR AND IT DID NOT RETURN, JUST STAYED DEPRESSED AGAINST THE FLOORBOARD. TOOK IT TO THE DEALERSHIP AND THEY SAID EVERYTHING IS FUNCTIONING AS DESIGNED. WELL ITS NOT! I CALLED CHRYSLER CUSTOMER SERVICE AND THEY TOLD ME THE CLUTCH IS ONLY UNDER WARRANTY FOR 12000 MILES. MY PREVIOUS 3 CARS HAVE BEEN MANUAL TRANSMISSIONS AND ALL WENT WELL OVER 100000K WITHOUT ANY CLUTCH ISSUES. MY CAR NOW DOES THIS REGULARLY AT LEAST ONCE EVERY OTHER DAY. I AM EXTREMELY DISAPPOINTED IN DODGE AND THOUGHT THEY WERE "FOCUSING ON QUALITY" LACK OF CONCERN BY DODGE REGARDING THIS SAFETY ISSUE IS DOWNRIGHT DISGUSTING. AFTER SPEAKING WITH THE CUSTOMER SERVICE REP SHE STATED SHE WOULD CONTACT THE DEALERSHIP AND CALL ME TOMORROW. NO CALL, NO E-MAIL. THEN THEY HAVE THE NERVE TO SEND ME A SURVEY ON HOW WAS MY ISSUE RESOLVED. IT WASN'T THAT'S WHY YOU GOT ALL 1'S. WHY DON'T YOU ACTUALLY STAND BY YOUR PRODUCT? *TR
- n. 5/18/2014 WENT TO START MY CAR AND THE CLUTCH PEDAL WENT STRAIGHT TO THE FLOOR ALMOST LIKE IT HAD NO FLUID IN THE MASTER CYLINDER AFTER I STARTED THE CAR I HAD TO SIT THERE AND PUMP IT TO FIND FEELING BEFORE I FELT COMFORTABLE DRIVING IT. THIS WAS STRANGE AS I PARK INSIDE A CLIMATE CONTROLLED GARAGE AND THERE IS NOT ANY FLUID LEAKING ON THE GROUND. *JS
- o. 6/3/2014 ON MULTIPLE OCCASIONS, WORSE WHEN IT IS HOT OUTSIDE, THE CLUTCH PEDAL WILL BE SOFT AND NOT COME UP OFF THE FLOOR. WHEN THE CLUTCH IS SOFT, I AM NOT ABLE TO SHIFT IN OR OUT OF GEAR. IF THE ENGINE IS ON AND IN GEAR, YOU CANNOT PUMP THE CLUTCH UNTIL THE VEHICLE IS OFF, OR IF YOU MANAGE TO GET IT INTO NEUTRAL. AS I PREFER TO PARK THE VEHICLE IN GEAR, WHEN THE CLUTCH GOES SOFT, IT MAKES IT DIFFICULT, IF NOT IMPOSSIBLE, TO REMOVE THE SHIFTER FROM GEAR TO PREVENT THE CAR FROM MOVING AND HITTING AN OBJECT. I HAVE ALMOST HIT A CONCRETE PILLAR AND DRIVEN THROUGH MY GARAGE WHEN THIS HAPPENS. I GET THE FEELING THE CLUTCH IS NOT FULLY DISENGAGED, DESPITE THE PEDAL STUCK ON THE FLOOR. WITHOUT PARKING IN GEAR, I RUN THE RISK OF THE CAR ROLLING AWAY IF THE PARKING BRAKE FAILS. THERE HAVE BEEN NO LEAKS AND THE DEALER HAS BEEN UNABLE TO LOCATE THE PROBLEM. *TR
- p. 6/5/2014 FOR THE PAST YEAR AND A HALF MY CLUTCH HAS

1

2

BEEN LOSING ALL RESISTANCE. THIS USUALLY HAPPENS WHEN THE VEHICLE IS COLD AND AT TIMES I AM UNABLE TO PUT MY CAR INTO GEAR. SOMETIMES THIS HAS HAPPENED WHILE AT STOP LIGHTS OR EVEN PULLING OUT INTO TRAFFIC. EVERY TIME I TAKE MY VEHICLE TO THE DEALERSHIP AIM TOLD THERE IS NOTHING WRONG. EVENTUALLY THEY REPLACED MY CLUTCH MASTER CYLINDER ABOUT 8 MONTHS AGO THE FIRST TIME. PROBLEM SEEMED TO RESOLVE THEN ABOUT 2 MONTHS AGO IT STARTED DOING IT AGAIN. WENT BACK TO THE DEALERSHIP AND TOLD NOTHING WAS WRONG. AFTER MULTIPLE TRIPS TO DEALERSHIP THEY FINALLY AGREED TO REPLACE MASTER CYLINDER AND DISCOVERED THE SLAVE CYLINDER IS LEAKING. VEHICLE BACK IN THE SHOP FOR THE PAST WEEK REPLACING SLAVE CYLINDER. ANY PERSPECTIVE DART BUYERS OUT THERE, I REALLY CAUTION AGAINST THIS PURCHASE. THIS IS ONLY ONE OF MULTIPLE ISSUES I HAVE HAD. ON A SIDE NOTE, I PURCHASED THIS VEHICLE NEW IN JULY 2012 WITH 120 MILES ON IT. SINCE THEN I HAVE HAD 2 IGNITION COILS REPLACED, 2 CLUTCH MASTER CYLINDERS, SLAVE CYLINDER, 3 TURBOS, CATALYTIC CONVERTER ALL REPLACED. BUYER BEWARE. *TR

- q. 6/6/2014 I WENT TO MOVE MY CAR AND THE CLUTCH WAS STUCK TO THE FLOOR OF MY CAR. I COULD NOT GET IT IN OR OUT OF GEAR. SO FAR CHRYSLER HAS REPLACED THE ELECTRICAL/COMPUTER PART, THE PART FOR THE CLUTCH. I JUST FOUND OUT ABOUT THE RECALL FOR THE BRAKE AND TRANSMISSION. LAST MY DOOR IS DARKER THEN THE REST OF THE CAR AND THEY ARE HAVING IT PAINTED. *TR
- r. 6/24/2014 2013 DODGE DART. CONSUMER WRITES IN REGARDS TO TRANSMISSION MALFUNCTION, BROKEN TIRE SENSOR AND OTHER VEHICLE PROBLEMS. *SMD THE CONSUMER STATED THE TRANSMISSION HAS BEEN ON GOING SINCE, THE FIRST DAY THE VEHICLE WAS PURCHASED. APPARENTLY, IT WAS A FACTORY DEFAULT, THAT COULD NOT BE FIXED. THE TRANSMISSION DOWN SHIFTED INTO SECOND GEAR, THE CLUTCH WOULD STICK, THE GEARS WERE GRINDING WHEN IN REVERSE AND A METALLIC NOISE WAS HEARD WHEN DOWN SHIFTING IN ANY GEAR THE DEALER REPLACED THE SECOND GEAR AND SYNCHRONIZERS. THE SUN VISOR NO LONGER STAYED IN ITS POSITION.
- s. 7/1/2014 I HAVE FILED A COMPLAINT IN SEPT. 2013 THE INCIDENT NUMBER WAS 10542516. I MY VEHICLE WAS TOWED TO THE NEAREST DEALERSHIP FOR REPAIR. THE CLUTCH PEDAL WOULD NOT RETURN ONCE DEPRESSED. IT WAS DETERMINED THAT IT WAS THE SLAVE CYLINDER. THAT WAS REPLACED, TAKING OVER A WEEK. THE REMEDIED THE PROBLEM UNTIL THE END OF JUNE 2014 WHEN THE CAR BEGAN DISPLAYING THE SAME PROBLEM.

27

28

I WAS GETTING ON THE INTERSTATE AND WENT TO SHIFT FROM 2ND TO 3RD AND THE CLUTCH PEDAL REMAINED DEPRESSED ONCE AGAIN. NOT HAVING POWER AT THIS KEY POINT OF ACCELERATION WAS DANGEROUS AND I WAS ALMOST REAR ENDED BY A SEMI. I TOOK THE CAR TO A DEALERSHIP ONCE AGAIN AND IT WAS DETERMINED THE SLAVE CYLINDER WAS THE PROBLEM ONCE AGAIN. I THINK THIS REALLY NEEDS TO BE EXAMINED AS IT CREATES A SERIOUS POTENTIAL FOR INJURY. *TR

- t. 7/3/2014 CLUTCH PEDAL DOES NOT RETURN FROM DEPRESSED POSITION. CLUTCH PEDAL IS SOFT AND CLUTCH MECHANISM DOES NOT FUNCTION PROPERLY FOR A FEW MINUTES OF INITIAL OPERATION. AFTER THE INITIAL INCIDENT THIS PROBLEM HAS BECOME MORE FREQUENT AND NOW OCCURS ALMOST DAILY. *TR
- u. 7/7/2014 I WAS ACCELERATING FROM A STOPPED POSITION AND WAS SHIFTING INTO FOURTH GEAR WHEN THE CLUTCH PEDAL STAYED DEPRESSED TO THE FLOOR. I HAVE HAD THIS CAR BACK FROM THE DEALER 10 DAYS. IT WAS IN THE SERVICE DEPARTMENT TO CORRECT THE SAME PROBLEM. THIS IS THE THIRD TIME THIS CAR HAS DONE THIS. THE CASE NUMBERS FOR THE FIRST TWO ARE 10542516 AND 10607620. LIKE THE SECOND EPISODE, I WAS LEFT IN A VULNERABLE SITUATION IN WHICH I WAS ALMOST HIT. THE LANES TAPER FROM TWO DOWN TO ONE AND I WAS IN THE INSIDE LANE COMING OUT OF THE TAPER. A TRUCK COMING UP FROM BEHIND WAS UNAWARE TO THE SLOW SPEED OF MY CAR AND I WAS NOT ABLE TO ACCELERATE. HE WAS ABLE TO SWERVE ACROSS THE NO PASSING LINES INTO ANOTHER LANE AND AVOID HITTING THE BACK OF MY CAR. I WAS ABLE TO COAST TO NEXT CROSS ROAD AND JUST MAKE IT OFF THE STATE HIGHWAY. MY VEHICLE WAS TOWED BACK TO THE DEALERSHIP. *JS
- v. 7/9/2014 DRIVING AT A AVERAGE SPEED OF 60-70 WHEN PASSING ON THE HWY MY CLUTCH PEDAL WAS STUCK TO THE FLOOR AND I HAD TO PULL IT OUT WITH MY FOOT TO CHANGE GEARS. THIS NOW HAS STARTED HAPPENING ON TAKE OFFS NOW. THE DEALER HAS ALL READY REPLACE IT ONCE AND IT IS STILL HAVING THE SAME ISSUE. APPARENTLY THE PART IS ON BACK ORDER BECAUSE THEY CAN NOT KEEP ENOUGH IN STOCK FOR THE CARS THAT ARE HAVING THIS REPLACED. IT TOOK 21 DAYS IN ORDER FOR MY PART TO ARRIVE AT THE DEALERSHIP. NOW I HAVE TO WAIT LONGER FOR A NEW ONE TO REPLACE THE ONE THAT WAS PUT IN. THIS CAN CAUSE A SERIOUS ISSUE ALMOST LIFE THREATENING BECAUSE YOU COULD BE PULLING OUT INTO TRAFFIC AND GOD FORBID YOU CAN'T REACT FAST ENOUGH. *JS
- w. 8/29/2014 THE CLUTCH PEDAL STUCK TO THE FLOOR PREVENTING ME FROM BEING ABLE TO SHIFT OUT OF

25

26

27

28

GEAR OR DISENGAGE THE ENGINE FROM THE TRANSMISSION. BECAUSE I AM A MECHANIC I WAS ABLE TO AVOID A CRASH. THIS IS A COMPLEX ISSUE AND MOST CONSUMERS WILL FREAK OUT IF THEY CAN NOT PUT THERE VEHICLE IN NEUTRAL AND THE ENGINE STALLS FROM THEM TRYING TO USE THE BRAKES. *TR

- x. 10/14/2014 MY FOOT WAS ON MY CLUTCH AND BRAKE I THEN STARED THE CAR....THE CAR LUNGE FORWARD INTO SOME BUSHES .. AFTER THAT THE CLUTCH STAYED ON THE FLOOR UNABLE TO SHIFT IN REVERSE TILL I PUMPED BRAKE AND CLUTCH I ACTUALLY LIFTED THE CLUTCH UP WITH MY FOOT TO USE IT TO SHIFT. *TR
- y. 1/13/2015 TL* THE CONTACT OWNS A 2013 DODGE DART. UPON STARTING THE VEHICLE OR DURING COLD WEATHER TEMPERATURES, THE CLUTCH FAILED TO SHIFT PROPERLY. THE CONTACT MENTIONED THAT THE CLUTCH NEEDED TO BE PUMPED IN ORDER TO SHIFT PROPERLY. THE VEHICLE WAS TAKEN TO DEALER WHERE THE FAILURE WAS UNABLE TO BE DUPLICATED. THE VEHICLE WAS NOT REPAIRED. THE MANUFACTURER WAS MADE AWARE OF THE FAILURE. THE APPROXIMATE FAILURE MILEAGE WAS 12,000.
- z. 1/22/2015 I WAS DRIVING AT ABOUT 40 MPH AND ABRUPTLY THE ENGINE STALLED AND THE CLUTCH WENT TO THE FLOOR AND THE VEHICLE REFUSED TO CHANGED GEARS OR MOVE. I ALLOWED IT TO VEER TO THE SIDE TO ESCAPE BEING REAR ENDED OR CRASHED FROM BEHIND. I HAD NO CONTROL OF THIS CAR. *TR
- aa. 2/19/2015 PURCHASED CAR BRAND NEW. HAVE DRIVEN MANUAL TRANSMISSIONS FOR 40 YEARS AND HAVE NEVER RUINED A CLUTCH OR ANY PART OF TRANSMISSION. I WAS DRIVING ALL THE ROAD AND GOING UP A HILL AND ATTEMPTED TO DOWNSHIFT TO GET UP THE STEEP HILL. THE CLUTCH WENT DOWN TO THE FLOOR AND THE SHIFTER WOULDN'T ALLOW SHIFTING. I VEERED OFF THE ROAD AND CALL TOW TRUCK. I HAD CAR TOWED TO LANDMARK DODGE, TOW MORROW, GA 30260, AND AFTER WEEKS THEY SAY THE ENTIRE TRANSMISSION WAS BURNED UP AND BROKEN INTO PIECES?? WELL, 1ST WEEK THEY ORDERED WRONG PART, 3 WEEK THEY SAID THEY HAD TO REMOVE THE ENTIRE TRANSMISSION AND TODAY (4 WEEKS LATER) THEY SAID THEY FEEL IT IS A CASE OF CUSTOMER ABUSÉ AND WANT 1500.00 TO REPAIR. I TOLD THEM UP FRONT A CERTIFIED TECHNICIAN LOOKED AT THE ISSUE PRIOR TO ME HAVING PULLED TO THEM AND HE SAID, "THIS IS DEFECTIVE". HE ALSO PRINTED OUT INFO FROM THE INTERNET OF OTHER DODGE DART 2012-2013 WITH THE VERY SAME ISSUE. CLUTCH TO THE FLOOR, AND EVEN A CLASS ACTION SUIT. I WILL HAVE TO GET IT FIXED

25

26

27

28

bb.4/15/2015 CLUTCH WENT COMPLETELY TO THE FLOOR AND HAD TO VEER CAR INTO A TERRAIN IN ORDER TO AVOID BEING RUN OVER BY DUMP TRUCK DIRECTLY BEHIND. THERE WAS NO WARNING AND CAR IS FAIRLY NEW. (WAS PURCHASED NEW). QUICK INVESTIGATION, AND THERE IS A LAW SUIT WITH CHRYSLER INDICATING THEY ARE AWARE OF THIS DEFECT BUT THEIR DEALERSHIPS ARE NOT AND REFUSED TO REPAIR WITHOUT CHARGING. INSISTED I TAKE CAR TO ANOTHER PLACE THAT REALLY WORKS ON DODGES (???). THIS LOST OF GEAR SHIFTING IS GOING TO GET SOMEONE KILLED! UNFORTUNATELY IT IS HARD TO REACH ME BY TELEPHONE BUT I WOULD REALLY LIKE TO HAVE SOME DETAILS AS TO HOW TO HANDLE THIS ISSUE. I HAD AN INDEPENDENT DEALER "WHO REALLY WORKS ON DODGES" TO REPAIR AND THEY CONFIRMED THE CLUTCH WAS DEFECTIVE AND CAUSED IT TO CRASH AND BURN. I'M NOT THE ONLY ONE WHO EXPERIENCED THIS.

cc. 5/13/2015 I WENT TO GET IN MY CAR TO GO TO WORK AND WHEN I STARTED MY CAR THE CLUTCH PEDAL WENT TO THE FLOOR AND WOULD NOT COME BACK UP. THE VEHICLE GOT STUCK IN FIRST GEAR UNTILL I MANUALLY BENT DOWN AND PULLED THE CLUTCH PEDAL UP AND TURNED THE CAR OFF SEVERAL TIMES. WHEN I SOPKE TO DODGE THEY ACTED LIKE THEY HAD NEVER HEARD OF THIS ISSUE (WHICH I KNOW IS NOT TRUE FROM VARIOUS FORUMS AND COMPLAINTS IVE SEEN). NOW I AM WORRIED ABOUT THE SAFTEY OF THE CAR BECASUE IF THIS HAPPENS WHILE IM ON THE ROAD AND NOT PARKED I OR SOMEONE COULD GET SERIOUSLY INJURED. THE DODGE DEALER I SPOKE WITH SAID TO FIX THE ISSUE I WOULD HAVE TO REPLACE THE MASTER CYLINDER, SLAVE CYLINDER, AND REPLACE THE CLUTCH. I DON'T FEEL I SHOULD HAVE TO WORRY ABOUT THIS THERE SHOULD BE A RECALL ISSUED.

dd.5/20/2015 CLUTCH PEDAL DEPRESSED AND WOULD NOT RETURN TO NORMAL POSITION. PRESSING DOWN ON CLUTCH PEDAL WOULD NOT DISENGAGE THE CLUTCH FROM THE FLYWHEEL SO CONTINUED TO ATTEMPT TO MOVE FORWARD REQUIRING FOOT MORE STRONGLY ON THE BRAKES. THIS WASN'T THE ONLY TIME, AND SEEMS TO OCCUR AFTER THE VEHICLE HAS BEEN SITTING A FEW HOURS. ITS GETTING FREQUENT ENOUGH THAT I'M GOING TO TRY TO TRADE THE VEHICLE IN. I DON'T TRUST CHRYSLER/DODGE PRODUCTS ANY MORE AND THEIR QUALITY IS GOING DOWN HILL WITH THEIR DRIVE BY WIRE VEHICLES. FOR THE RECORD, 90% OF MY MILEAGE IS ALL HIGHWAY AND I DON'T "POP" THE CLUTCH TO PEAL OUT AT STOP LIGHTS AND THE LIKE. SEARCHES OF THE INTERNET ARE FINDING MORE AND MORE POSTS WITH CLUTCH AND TRANSMISSION PROBLEMS.

ee. 6/3/2015 WHEN FIRST STARTED ON A COOL OR COLD

MORNING, THE CLUTCH ON THE 2013 DODGE DART WILL NOT HAVE ANY PRESSURE AND STICK TO THE FLOOR. THE CLUTCH PEDDLE WOULD HAVE TO BE PHYSICALLY PULLED UP FROM THE FLOOR AND PUMPED TO DEVELOP ANY PEDDLE. THE VEHICLE WAS TAKEN TO THE DEALER THAT COULD NOT REPLICATE THE PROBLEM NOR WOULD MAKE ANY INDICATION TO MAKE THE REPAIR. THE NEXT WEEK (AROUND MAY 18, 2015), THE MANUAL TRANSMISSION WAS PARKED IN FIRST GEAR AND WHEN 18, THE CLUTCH WAS DEPRESSED, THERE WAS LITTLE TO NO PEDDLE. THE CAR STARTED AND BEGAN TO LUNGE FORWARD AND STOPPED. THE CLUTCH ALMOST STUCK TO THE FLOOR. . OTHER TIMES, THE CAR IS PARKED IN NEUTRAL AND THE CAR WILL NOT ALLOW THE DRIVER TO SHIFT INTO GEAR. THERE IS FLUID VISIBLE ON TOP OF THE TRANSMISSION WHICH IS SUSPECTED BY THE OWNER TO BE FROM THE HYDRAULIC CLUTCH. CHRYSLER IS AWARE OF THIS PROBLEM AND ARE BEING SUED IN THE STATE OF CALIFORNIA OVER OTHER CLAIMS. THIS IS A SAFETY THESE CARS VOLUME OF **ISSUE** WITH THE AND COMPLAINTS FOR THE SAME ISSUE IS INDICATIVE OF A LARGER PROBLEM.

- ff. 6/8/2015 TL* THE CONTACT OWNS A 2013 DODGE DART. WHILE DRIVING AT APPROXIMATELY 50 MPH, THE CLUTCH PEDAL WAS DEPRESSED AND FAILED TO RESPOND WITHOUT WARNING. THE VEHICLE WAS TAKEN TO A DEALER WHERE IT WAS DIAGNOSED THAT THE MASTER SLAVE CYLINDER NEEDED TO BE REPLACED. THE VEHICLE WAS REPAIRED HOWEVER, THE FAILURE RECURRED. THE MANUFACTURER WAS NOTIFIED OF THE FAILURE. THE FAILURE MILEAGE WAS 1,200.
- gg.6/8/2015 TL* THE CONTACT OWNS A 2013 DODGE DART. WHILE REVERSING OUT OF A PARKING LOT AT 5 MPH, THE CLUTCH FAILED TO SHIFT OUT OF REVERSE TO GO INTO FIRST GEAR. THE FAILURE RECURRED ONCE. THE VEHICLE WAS TAKEN TO A DEALER, BUT WAS NOT DIAGNOSED OR REPAIRED. THE MANUFACTURER WAS MADE AWARE OF THE FAILURE. THE FAILURE MILEAGE WAS 24,000.
- hh.6/10/2015 2013 DART 2.0 LITER, 6 SPEED MANUAL TRANS. CLUTCH PEDAL GOES TO FLOOR WITH NO RESISTANCE AND WILL NOT DISENGAGE CLUTCH. PULLING THE PEDAL UP WITH FOOT AND PUMPING IT RESTORES FUNCTION UNTIL THE CAR IS PARKED AT WHICH TIME, THE SYSTEM BLEEDS DOWN AGAIN AND THE PEDAL GOES TO THE FLOOR WITHOUT DISENGAGING THE CLUTCH. PROBLEM IS MARKEDLY WORSE IN HOT WEATHER. RESPONSE FROM CHRYSLER ON RECTIFICATION ACTION IS AWAITING FOLLOWING INQUIRY BY MYSELF.
- ii. 6/12/2015 I WENT AND ATTEMPTED TO START THE CAR. CAR WOULD NOT START. IT WAS LIKE THE CLUTCH WOULD NOT ENGAGE. RELEASED THE CLUTCH AND RE-ENGAGED,

25

26

27

28

AND IT STARTED. DURING SHIFTS, IT DIDNT WANT TO GO INTO 3 OR 6TH GEARS. IT WAS LIKE THE CLUTCH IS NOT ENGAGING ONCE AGAIN. TOOK THE CAR BACK TO WHERE I PURCHASED IT, PERFORMANCE DODGE, AND THEY TOLD ME THAT CHRYŚLER KNOWS OF THE ISSÚE BUT CHRYSLER STAR WILL NOT FIX IT. I ASKED HOW CAN THEY KNOW THAT THE CLUTCH HAS ISSUES, BUT THEY ARE NOT GOING TO FIX IT. THE EMPLOYEE INFORMED ME THAT THEY ALL ARE LIKE THIS. CHRYSLER KNOWS OF THE CLUTCH ISSUES DUE TO ALL THE COMPLAINTS, BUT THEY STILL RISK THE LIVES OF THE INDIVIDUALS WHO PURCHASED THE VEHICLE BY NOT REPLACING THE CLUTCH. I HAVE ALSO HAD ISSUES WITH MY WINDOWS NOT ROLLING UP OR DOWN AND THE RADIO KEEPS RESETTING ITSELF. THEY DO UPDATES, BUT IT DOES NOT FIX THE RADIO ISSUE. THE LAST TIME I TOOK IT FOR THE UPDATE, THE UPDATE WOULDNT EVEN LOAD TO FIX THE ISSUE. HOW CAN A COMPANY KNOW OF ISSUES BUT REFUSE TO FIX THEM?

- jj. 6/14/2015 I DEPRESSED THE CLUTCH TO START THE ENGINE AND WHEN IT STARTED THE CAR BEGAN TO MOVE EVEN THOUGH THE CLUTCH PEDAL WAS FULLY DEPRESSED. I HAD TO TURN THE ENGINE OFF TO STOP THE CAR FROM MOVING AND THE CLUTCH PEDAL REMAINED ON THE FLOOR. AFTER A FEW MORE ATTEMPTS IT STARTED TO WORK CORRECTLY. IT NOW DOES THIS EVERY TIME IT IS PARKED FOR A FEW HOURS. VERY DANGEROUS DEFECT THAT NEEDS TO BE RECALLED BY CHRYSLER.
- kk.6/20/2015 CLUTCH PEDAL KEPT GETTING STUCK IN POSITION AND WOULD NOT DISENGAGE.
- II. 7/20/2015 WHEN GETTING INTO MY CAR IN THE MORNING OR AFTER WORK (ANY TIME THE CAR HAS BEEN SITTING FOR A WHILE), THE CLUTCH PEDAL GOES STRAIGHT TO THE FLOOR AND DOESN'T COME BACK UP. I CANNOT PUT MY CAR INTO GEAR OR EVEN START THE CAR. I HAVE TO PUMP THE CLUTCH PEDAL FOR A FEW MINUTES UNTIL I HAVE A LITTLE PRESSURE TO EVEN START MY CAR. MY CAR STALLED OUT TWICE FROM THIS WHEN ENTERING A PARKING GARAGE AND I ALMOST HIT ANOTHER CAR BECAUSE OF THIS. AFTER DRIVING THE CAR FOR 2-3 MILES THE CLUTCH SEEMS TO COME BACK TO NORMAL PRESSURE AND I CAN SHIFT FINE AT THAT POINT.
- mm. 7/27/2015 I HAVE A 2013 DODGE DART RALLYE. I BOUGHT IT USED IN JANUARY 2015. IT HAS THE 1.4 MULTI AIR TURBO WITH 6 SPD MANUAL TRANSMISSION. MY PROBLEM IS JUST ABOUT EVERY MORNING OR AFTER THE CAR SETS FOR A FEW HOURS WHEN I TRY TO START THE CAR I PUSH THE CLUTCH PEDAL IN TO START THE CAR AND I GO TO PUT THE CAR IN GEAR AND IT WON'T GO IN GEAR WITH MY CLUTCH PEDAL TO THE FLOOR AND THE CAR TRYS TO MOVE WHEN I TRY TO PUT IT IN GEAR SO I LET OFF THE CLUTCH AND IT STICKS HALF WAY TO THE FLOOR

28

SO I HAVE TO PUMP IT FOR ABOUT 2 MINUTES OR UNTIL THE CAR WARMS UP JUST TO PUT IT IN GEAR I DID RESEARCH ON THIS AND APAIRENTLY ALOT OF PEOPLE WITH THIS CAR HAVE BEEN HAVING THIS SAME PROBLEM AND CHRYSLER WANTS TO CHARGE ME JUST TO TAKE A LOOK AT IT BECAUSE IT IS OUT OF WARRANTY THIS ISSUE REALLY NEEDS TO BE LOOKED INTO.

- nn.8/6/2015 INTERMITTENTLY, THE CLUTCH PEDAL HAD DROPPED TO THE FLOOR WHEN DEPRESSED AND NOT RETURNING WITHOUT PUMPING THE PEDAL PRIOR TO STARTING THE ENGINE. THIS WAS BECOMING COMMON AFTER THE CAR WAS NOT IN OPERATION OVERNIGHT BUT ON 6-AUG-15 THE WHILE DRIVING AT HIGHWAY SPEEDS PRIOR TO EXITING A LIMITED ACCESS HIGHWAY WITH THE PEDAL DEPRESSED TO THE FLOOR THE ENGINE DID NOT DISENGAGE FROM THE TRANSMISSION OR ALLOW THE SHIFTER TO BE MOVE OUT OF GEAR. IT REQUIRED THE PEDAL TO BE PULLED UP MANUALLY WITH THE TOE OF MY SHOE AND PUMPED BEFORE IT ACTUATED THE CLUTCH AND ALLOWED THE CAR TO STOP. AN ACCIDENT WAS NARROWLY AVOIDED ON INTERSTATE 495 DUE TO THIS FAILURE. CHRYSLER WAS CONTACTED REGARDING THE SERVICE BULLETIN M37, TRANSAXIAL SLAVE VALVE DEFECT AND THEY SAID THIS IS A LISTED ISSUE FOR THE CAR/ENGINE BUT NOT FOR THIS VIN. REGARDLESS OF THE BULLETIN'S "COMMITMENT TO SAFETY" THEY WOULD NOT COVER ANY TOWING OR REPAIR.
- 00.8/6/2015 WHEN TRYING TO START THE CAR THE CLUTCH PEDAL WILL GET STUCK DOWN AND NOT ENGAGE. IF THIS HAPPENS WHEN DRIVING IT COULD CAUSE AN ACCIDENT.
- pp.8/14/2015 WHEN I WENT TO TURN MY CAR ON, WHICH IS A MANUAL, MY CLUTCH PEDAL STAYED ENGAGED AND WOULD NOT RELEASE AND MY CAR WOULD NOT TURN OFF. I COULD NOT TURN THE KEY TO TURN THE CAR OFF. I HAD TO WAIT A FEW MINUTES BEFORE THE CLUTCH RELEASED AND I WAS FINALLY ABLE TO TURN MY CAR OFF. WHEN I TRIED AGAIN TO TURN MY CAR ON THE CLUTCH PEDAL ONCE AGAIN STAYED ENGAGED AND WOULD NOT RELEASE BUT I WAS ABLE TO TURN MY CAR OFF THE SECOND TIME. AND TRY AGAIN AND AGAIN UNTIL THE CLUTCH WOULD RETURN AFTER I TURNED THE CAR ON
- qq.8/26/2015 WHEN TRYING TO START THE CAR, THE CLUTCH PEDAL WILL GET STUCK DOWN AND NOT ENGAGE INTERMITTENTLY. THE CLUTCH PEDAL DROPS TO THE FLOOR WHEN DEPRESSED AND NOT RETURNING WITHOUT PUMPING THE PEDAL PRIOR TO STARTING THE ENGINE. THIS IS BECOMING COMMON AFTER THE CAR IS NOT IN OPERATION OVERNIGHT
- rr. 8/27/2015 THIS HAS BEEN AN ONGOING-INTERMITTENT

25

26

27

28

THE HYDRAULIC CLUTCH PROBLEM/ISSUE. **SYSTEM** (MANUAL TRANS) WILL LOSE PRESSURE WHICH MEANS THAT THE CLUTCH PEDAL WILL GO TO THE FLOOR AND I CAN'T SHIFT THE TRANSMISSION. AT TIMES IT IS ONLY DOING THIS FIRST THING IN THE MORNING BUT WILL GET PRESSURE AFTER "PUMPING IT UP" A FEW TIMES. IT WILL LOSE PRESSURE AFTER DRIVING FOR A PERIOD OF 15-20 MINUTES MEANING THAT WHEN COMING TO A STOP I AM UNABLE TO DOWNSHIFT. ONCE STOPPED, WHEN IT HAS LOST PRESSURE, IF YOU LEAVE THE TRANSMISSION IN FIRST GEAR, OR REVERSE, IT WILL MOVE WHEN THE IGNITION KEY IS PUT INTO THE START MODE WHEN THE CLUTCH PEDAL IS FULLY DEPRESSED! THERE HAVE NEVER BEEN ANY FLUID LEAKS OR SIGNS THAT THE LEVEL HAS GONE DOWN. I HAVE SEEN ON A DODGE DART OWNERS WEBSITE THAT THIS IS A PROBLEM THAT OTHERS HAVE HAD AS WELL.

ss. 9/29/2015 ONGOING CLUTCH/HYDRAULIC PROBLEMS HAVE CAUSED ME TO BE IN SEVERAL UNSAFE SITUATIONS. FIRST SAFETY CONCERN WAS DUE TO CAR STALLING WHEN ATTEMPTING TO ACCELERATE FROM A STOP. THERE WERE SEVERAL TIMES THAT IMPROPER CLUTCH ENGAGEMENT CAUSED THE CAR TO JERK AND DIE AT A STOP. SECOND CONCERN WAS FROM DIFFICULTY SHIFTING GEARS IN STOP AND GO TRAFFIC DUE TO CLUTCH NOT ENGAGING FULLY. THIRD CONCERN WAS FROM TOTAL SYSTEM FAILURE (19426 MILES): EXITED INTERSTATE HIGHWAY AND DEPRESSED CLUTCH TO SHIFT TO NEUTRAL. WHILE DEPRESSING THE CLUTCH I HEARD A LOUD POP/CLUNK SOUND AND THE CLUTCH INSTANTLY DROPPED TO THE FLOOR. I THEN STARTED SMELLING THE CLUTCH BURNING AND HAD NO ABILITY TO SHIFT OR ENGAGE GEARS. I WAS LEFT IN THE MIDDLE OF THE ROADWAY AND HAD TO PUSH MY VEHICLE TO A SAFE LOCATION ON THE SHOULDER OF THE ROAD THANKS TO THE HELP OF SOME PEOPLE THAT TOWING VEHICLE AFTER THE DEALERSHIP FOR REPAIR, I WAS TOLD THE FLYWHEEL. PRESSURE PLATE, AND CLUTCH NEEDED TO BE REPLACED (19,426 MILES). FOURTH CONCERN WAS A FAILURE OF THE CLUTCH (APPROX 34,735 MILES): AFTER BACKING OUT OF A DRIVEWAY THE CLUTCH STUCK TO THE FLOOR AND WOULD NOT RETURN TO THE NORMAL POSITION CAUSING THE INABILITY TO SHIFT. AFTER RESTARTING VEHICLE I HAD TO LIFT CLUTCH BY HAND AND PUMP CLUTCH TO REGAIN HYDRAULIC PRESSURE. I WAS TOLD CLUTCH HAD FAILED AND WAS BLAMED FOR FAILURE FROM RIDING MILEAGE PROBLEMS CLUTCH **FIRST** REPORTED CONTINUED TO MENTION PROBLEMS ON LATER VISITS): 1555 - NOISE RELEASING CLUTCH 2072 - RESISTANCE AND **CHANGING** ENGAGEMENT IN THE CLUTCH MILEAGE/REPAIRS 5905 MADE: **MASTER** 19426 CYLINDER/ACTUATOR REPLACED CLUTCH. PRESSURE PLATE, AND FLYWHEEL REPLACED 34747 - CLUTCH, PRESSURE PLATE, FLYWHEEL, AND SLAVE

CYLINDER REPLACED (AWAITING AMENDED REPAIR ORDER) AFTER LATEST REPAIR THE CAR IS BACK IN SHOP DUE TO RETURNED HYDRAULIC PRESSURE VARIANCE

- tt. 12/4/2015 I HAVE A 2013 DODGE DART. AFTER 2 YEARS, THE CLUTCH SUDDENLY STUCK TO THE FLOOR, THE VEHICLE INOPERABLE; IT NEEDED A NEW MASTER CYLINDER. A FEW MONTHS LATER, I STARTED NOTICING IT STICKING AGAIN, BUT IT COULD BE PULLED OUT BY USING MY FOOT TO POP IT BACK OUT. SO I PROMPTLY TOOK IT TO THE DEALER. THEY SAID EVERYTHING WAS NORMAL. LAST MONTH, THE CLUTCH WENT OUT AGAIN. HAD TO BE TOWED TO THE DEALER. NOW IT SEEMS THEY ARE REPLACING THE ENTIRE CLUTCH KIT. TOLD ME THE FLYWHEEL WAS COMPLETELY BURNED OUT. AND TRIED TO BLAME MY DRIVING, SAYING THE FLYWHEEL WAS NORMAL WHEN THEY EVALUATED IT. NO WAY, DODGE. NOW THEY'VE HAD MY CAR SINCE NOVEMBER 16TH, TODAY BEING DEC. 3, AND IT STILL WON'T BE FIXED UNTIL WELL INTO NEXT WEEK. AND THE RENTAL CAR IS OUT OF MY POCKET.
- uu.12/23/2015 CAME UP TO A STOP SIGN, DROVE OFF AND WENT TO SHIFT INTO 2ND (STANDARD TRANSMISSION) AND MY SHIFTER WAS LOOSE. GEAR IS STUCK IN FIRST.
- vv.1/4/2016 CLUTCH PEDAL DOES NOT RETURN FROM DEPRESSED POSITION. CLUTCH PEDAL IS SOFT AND CLUTCH MECHANISM DOES NOT FUNCTION PROPERLY FOR A FEW MINUTES OF INITIAL OPERATION. AFTER THE INITIAL INCIDENT THIS PROBLEM HAS BECOME MORE FREQUENT AND NOW OCCURS ALMOST DAILY.
- ww. 1/26/2016 1) SLAVE CYLINDER IN TRANSMISSION (MANUAL) BEGAN FAILING AT 12,000 MILES, CAUSING CLUTCH PEDAL TO LOSE PRESSURE AND NOT RETURN TO TOP OF TRAVEL. UNABLE TO SHIFT INTO ANY GEAR. THIS OCCURRED WHEN PARKED OVERNIGHT. DEALERSHIP REPLACED SLAVE CYLINDER, CLUTCH, AND THROW OUT BEARING WITH NO CHARGE.
- xx.2/10/2016 CAR SHIFTS OUT OF GEAR, HAS LITTLE POWER, SERVICE LIGHT COMES ON ,WILL NOT START AT TIMES, TAKEN TO DEALERS FOR RECALL R42 TWICE PARTS NOT AVAILABLE. NOW THEY ARE SAYING A WHOLE NEW TRANSMISSION IS NEEDED AT A COST OF OVER 8 THOUSAND DOLLARS. CLUTCH PLATE CRACKED AND FLY WHEEL DAMAGED. TRYING TO BLAME MY DRIVING, HAD TO BE TOWED.
- yy.3/4/2016 I GOT 2013 DODGE DART 1.4L TURBO 6 SPEED MANUAL AND EVERY MORNING WHEN LEAVE FOR WORK CLUTCH PEDAL GOES TO FLOOR AND HAVE TO PUMP IT GOOD BIT JUST TO GET IT TO CHANGE GEARS. STARTED CAR IN REVERSE AND CAR TAKES OFF WHILE ENGINE IS

2014 Dodge Dart

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

- a. 9/12/2014 TL* THE CONTACT OWNS A 2014 DODGE DART. WHILE DRIVING APPROXIMATELY 10 MPH, THE CLUTCH BECAME STUCK IN THE DOWNWARD POSITION AND THE GEAR SHIFTER WAS STUCK IN FIRST GEAR. THE CONTACT HAD TO DEPRESS THE CLUTCH COMPLETELY DOWN TO THE FLOORBOARD TO LOOSEN THE CLUTCH, FOLLOWED BY AGGRESSIVELY PULLING THE GEAR SHIFTER TO GET IT OUT OF FIRST POSITION. THE VEHICLE WAS NOT DIAGNOSED OR REPAIRED. THE MANUFACTURER WAS NOT NOTIFIED. THE VIN WAS UNAVAILABLE. THE APPROXIMATE FAILURE MILEAGE WAS 33,000.
- b. 1/29/2015 THE CLUTCH PEDAL WOULD STICK TO THE FLOOR IN COLD WEATHER. WOULD EASILY STALL BECAUSE OF POOR ENGAGEMENT. SOMETIMES THE CAR WOULD BUCK OR STUTTER BECAUSE THE CLUTCH WOULD NOT BE ABLE TO EFFECTIVELY ENGAGE. SOMETIMES THE VEHICLE WOULD STALL ON ENGAGEMENT AND HAVE TO SIT FOR SEVERAL MINUTES BEFORE THE ENGINE WOULD START. AFTER ATTEMPTED REPAIR THE ANTO CLUTCH HYDRAULICS BY CORWIN THE CLUTCH STILL HAS SLOP IN IT AND POOR WORKSMANSHIP WAS FOUND AT ANOTHER DEALER. THE TRANSMISSION IS NOW NOISY AND MAKES LOUD CLUNKING OR WHINING NOISES WHEN THE CLUTCH IS ENGAGED OR DISENGAGED. THE CLUTCH WILL STILL PARTIALLY STICK TO THE FLOOR IN SEVERE COLD AND IS NOT SAFE TO DRIVE. *TR
- c. 4/9/2015 PURCHASED A 2014 DODGE DART USED WITH A 6 SPEED. THIS INCIDENT HAPPENED JUST THREE WEEKS AFTER I PURCHASED IT. I NOTICED IT STARTED TO SLIP AND WHILE DRIVING DOWN THE HIGHWAY I HEARD A NOISE, CAR LOST POWER AND SMOKE STARTED POURING OUT FROM UNDER THE HOOD. I HAD IT TOWED TO THE DEALERSHIP WHERE I WAS INFORMED THAT SOMETHING FAILED IN THE CLUTCH, BLOWING A HOLE THROUGH THE TRANSMISSION. THIS ALL HAPPENED WITHIN A MINUTE OR SO WHILE DRIVING AT HIGHWAY SPEEDS.
- d. 7/27/2015 WHILE DRIVING CLUTCH WILL LOSE COMPRESSION MAKING IT DIFFICULT TO SHIFT WITHOUT GRINDING GEARS. CLUTCH WILL GO ALL THE WAY TO THE FLOOR AND INHIBITED YOU FROM SHIFTING. I HAVE HAD TO SHIFT INTO NEUTRAL TO SLOW DOWN HOPING THE CLUTCH REGAINS COMPRESSION IN ORDER TO SHIFT INTO APPROPRIATE GEAR. THIS ALSO INHIBITS PROPER ACCELERATION WHEN SHIFTING GEARS.

e. 9/15/2015 THE VEHICLE HAS A MANUAL TRANSMISSION. MY VEHICLE REVS WHEN ATTEMPTING TO SHIFT IT. THE CLUTCH WILL BE COMPLETELY UP AND THE VEHICLE WILL STILL REV AS IF IT IS ENGAGED. AT THIS POINT THERE IS NOTHING THAT CAN BE DONE UNTIL IT STOPS REVVING. IT ALSO GRINDS AND CLATTERS WHEN SHIFTING FROM 1ST TO 2ND AND 2ND TO 3RD GEAR. VERY ROUGH SHIFTING AND SOMETIMES EXPERIENCE A BURNING SMELL AFTER ITS DRIVEN.

70. Also, complaints posted by consumers in forums demonstrate that the defect is widespread and dangerous and that it manifests without warning. The complaints also indicate Defendant's awareness of the Clutch Defect and the dangerous conditions it creates. The following are some safety complaints relating to the Clutch Defect (spelling and grammar mistakes remain as found in the original) (Edmunds.com (May 25, 2016), http://www.edmunds.com/).

Edmunds.com

- a. Posted on 4/2/2016 by teddyluv: I too have thought about a lawyer, as I had the master cylinder replaced twice since Sept 2014, then in Jan of this year, the clutch went out, I was told that it was normal wear & tear, had nothing to do with the master cylinder& therefore cost me 2369.00 to repair. then it was back in the shop, the turbo went out on it..... had it back for 6 days when once again, the clutch pedal went to the floor & stayed there. For the THIRD time in 1 1/2 years my 2013 Dodge dart is Back in the shop to have the master cylinder replaced. Chrysler just says "I am sorry & refuses to work with me. Hello: Look at the cars history, I feel that Chrysler should step up & do the "Right" thing here. They do not seem to care about their customers, or realize just how much word of mouth advertising can hurt their business. I can't begin to tell you how many people I have already told about my issues, and they Will not be purchasing a vehicle from Chrysler/ Dodge because of it. I am amazed that there are so many issues with the Dodge dart & Chrysler is getting away scott free.
- b. Posted on 4/2/2016 by fireemt45: I have a 2015 Dodge Dart with 22000 miles on it. I started having problems with the car two weeks ago. The clutch would reengage while driving down the road at about 3000 rpms in third and fourth gear. That was the first couple days. I went to the dealer right away and I had to wait a week to get the car looked at. When I took the car to the dealer finally the clutch was doing it in all six gears. They looked at it and claim that it is normal wear and tear. They are paying for parts. I still dont understand how the clutch is out at 22000 miles. I have been driving a Manual since I started driving. Has anyone had a similair problem and what their dealer did to fix the problem. I see that theres quite a few

1 /

71. The Clutch Defect poses an unreasonable safety risk for Class Members, as well as the drivers, passengers, and pedestrians sharing the road with Class Vehicles. A driver's ability to change gears, and the driver's reliance on a vehicle's Clutch System to perform properly, are critical to safe vehicle operation. A defect that causes one or more of the problems described above poses a safety hazard to drivers and the general public because it increases the risk of accidents.

FCA Had Exclusive Knowledge of the Clutch Defect

- 72. FCA had superior and exclusive knowledge of the Clutch Defect, and knew or should have known that the defect was not known or reasonably discoverable by Plaintiffs and Class Members before they purchased or leased the Class Vehicles.
- 73. Plaintiffs are informed and believe and based thereon allege that before Plaintiffs purchased their Class Vehicle, and since at least early 2012, FCA knew about the Clutch Defect through sources not available to consumers, including pre-release testing data, early consumer complaints about the Clutch Defects to Chrysler and its dealers, testing conducted in response to those complaints, high failure rates and replacement part sales data, aggregate data from Chrysler dealers, among other internal sources of aggregate information about the problem.
- 74. Before the Class Vehicles were available for sale, FCA acknowledged in its own press releases the extensive pre-release testing and analysis it conducted before bringing the Fiat C635 manual transmission to the market. For example, on April 28, 2012, Chrysler posted a media release, where Bob Lee, Vice President, Engine and Electrified Propulsion Engineering Chrysler Group LLC, stated, "[t]he three new engines and transmissions

available in the new Dodge Dart have been designed and tested to meet consumer's needs for fuel economy, refinement, durability and power in a compact car." Additionally, each transmission was said to have undergone "extensive testing and evaluation to ensure that customer expectations in the area of refined shifting characteristics . . . are met."

- 75. FCA was also aware of the Clutch Defect through its experience with the same Fiat C635 manual transmission used in 2011-2012 Dodge Journey vehicles and the numerous complaints it received, both from consumers and from automotive journalists, who roundly criticized its performance.
- 76. On January 20, 2012, FCA issued TSB "06-001-12" for the 2011-2012 model year Dodge Journey vehicles equipped with the Fiat C635 manual transmission because the clutch pedal was inoperative in some vehicles.
- 77. Further, in or around November 2012, FCA issued service bulletin 10051770-2112 because certain 2013 Dodge Dart vehicles were equipped with defective clutch slave cylinders that could cause a hydraulic fluid leak and failure of the clutch pedal.
- 78. Then, on or around August 15, 2014, FCA released STAR case number S1406000001 to its dealers because the "Clutch Pedal Does Not Return (Remains on the Floor) After Depressing the Pedal" in Dodge Dart vehicles equipped with the Fiat C635 manual transmission. FCA instructed technicians to replace the clutch master cylinder. The same Star Case S1406000001 was rereleased on February 26, 2015, to instruct technicians to replace the reservoir hose as well. On August 24, 2015, a third version of Star Case S1406000001 was released, eliminating the "Parts Required" section and listing the master clutch cylinder and reservoir as discrete repairs.
- 79. Finally, in or around January 2016, FCA extended the clutch master cylinder and reservoir hose warranty period for 2013-2015 Dodge Dart vehicles

exhibiting a "loss of clutch pedal operation including limited pedal travel and limited clutch disengagement" and provided reimbursement for costs incurred by clutch master cylinder repairs. As discussed above, this campaign was incomplete because it omits other Clutch System components, including the Clutch Slave Cylinder, even though they are bathed in the same hydraulic fluid and subject to the same contamination that damages the clutch Master Cylinder.

- 80. The existence of the Clutch Defect is a material fact that a reasonable consumer would consider when deciding whether to purchase or lease a vehicle that was equipped with a manual transmission. Had Plaintiffs and other Class Members known that the Class Vehicles were equipped with defective Clutch Systems, they would not have purchased or leased the Class Vehicles equipped with the Clutch System or would have paid less for them.
- 81. Reasonable consumers, like Plaintiffs, reasonably expect that a vehicle's Clutch System is safe, will function in a manner that will not pose a safety hazard, and is free from defects. Plaintiffs and Class Members further reasonably expect that FCA will not sell or lease vehicles with known safety defects, such as the Clutch Defect, and will disclose any such defects to its consumers when it learns of them. They did not expect FCA to fail to disclose the Clutch Defect to them and to continually deny the defect.

FCA Has Actively Concealed the Clutch Defect

- 82. While it has been fully aware of the Clutch Defect in the Class Vehicles, FCA actively concealed the existence and nature of the defect from Plaintiffs and Class Members at the time of purchase, lease, or repair and thereafter. Specifically, FCA failed to disclose or actively concealed at and after the time of purchase, lease, or repair:
 - (a) any and all known material defects or material nonconformity of the Class Vehicles, including the defects relating to the

Page 36

Civ. Code §§ 1770(a)(5) & (7).

- 100. Defendant's unfair and deceptive acts or practices occurred repeatedly in Defendant's trade or business, were capable of deceiving a substantial portion of the purchasing public, and imposed a serious safety risk on the public.
- 101. Defendant knew that the Class Vehicles and their Clutch System suffered from an inherent defect, were defectively designed, and were not suitable for their intended use.
- 102. As a result of their reliance on Defendant's omissions, owners and/or lessees of the Class Vehicles suffered an ascertainable loss of money, property, and/or value of their Class Vehicles. Additionally, as a result of the Clutch Defect, Plaintiffs and Class Members were harmed and suffered actual damages in that the Class Vehicles' clutch components are substantially certain to fail before their expected useful life has run.
- 103. Defendant was under a duty to Plaintiffs and Class Members to disclose the defective nature of the Clutch System and/or the associated repair costs because:
 - (a) Defendant was in a superior position to know the true state of facts about the safety defect in the Class Vehicles' Clutch System;
 - (b) Plaintiffs and Class Members could not reasonably have been expected to learn or discover that their Clutch System had a dangerous safety defect until it manifested; and
 - (c) Defendant knew that Plaintiffs and Class Members could not reasonably have been expected to learn of or discover the safety defect.
- 104. In failing to disclose the defective nature of the Clutch System,

 Defendant knowingly and intentionally concealed material facts and breached its

duty not to do so.

- 105. The facts Defendant concealed from or failed to disclose to Plaintiffs and Class Members are material in that a reasonable consumer would have considered them to be important in deciding whether to purchase or lease the Class Vehicles or pay less. Had Plaintiffs and Class Members known that the Class Vehicles' Clutch Systems were defective, they would not have purchased or leased the Class Vehicles or would have paid less for them.
- 106. Plaintiffs and Class Members are reasonable consumers who do not expect the Clutch System installed in their vehicles to exhibit problems such as the clutch pedals "going soft" and remaining depressed to the floor, transmissions failing to engage or disengage, gear shifts burning out, the clutches and transmissions burning out, stalling, and failure to accelerate or decelerate. This is the reasonable and objective consumer expectation relating to vehicle clutches.
- 107. As a result of Defendant's conduct, Plaintiffs and Class Members were harmed and suffered actual damages in that, on information and belief, the Class Vehicles experienced and will continue to experience problems such as the clutch pedals "going soft" and remaining depressed to the floor, clutches failing to operate correctly and/or burning out, stalling, and failure to accelerate or decelerate.
- 108. As a direct and proximate result of Defendant's unfair or deceptive acts or practices, Plaintiffs and Class Members suffered and will continue to suffer actual damages.
 - 109. Plaintiffs and the Class are entitled to equitable relief.
- 110. Plaintiffs provided Defendant with notice of its violations of the CLRA pursuant to California Civil Code § 1782(a). Defendant failed to provide appropriate relief for their violations of the CLRA within 30 days. Therefore,

Plaintiffs seek monetary, compensatory, and punitive damages, in addition to injunctive and equitable relief.

SECOND CAUSE OF ACTION

(Violation of California Business & Professions Code § 17200, et seq.)

- 111. Plaintiffs incorporate by reference the allegations contained in the preceding paragraphs of this Complaint.
- 112. Plaintiffs bring this cause of action on behalf of themselves and on behalf of the California Sub-Class.
- 113. As a result of their reliance on Defendant's omissions, owners and/or lessees of the Class Vehicles suffered an ascertainable loss of money, property, and/or value of their Class Vehicles. Additionally, as a result of the Clutch Defect, Plaintiffs and Class Members were harmed and suffered actual damages in that the Class Vehicles' clutch components are substantially certain to fail before their expected useful life has run.
- 114. California Business & Professions Code § 17200 prohibits acts of "unfair competition," including any "unlawful, unfair or fraudulent business act or practice" and "unfair, deceptive, untrue or misleading advertising."
- 115. Plaintiffs and Class Members are reasonable consumers who do not expect their Clutch Systems to exhibit problems such as the clutch pedals "going soft" and remaining depressed to the floor, clutches failing to operate correctly and/or burning out, stalling, and failure to accelerate or decelerate.
- 116. Defendant knew the Class Vehicles and their transmissions suffered from inherent defects, were defectively designed or manufactured, would fail prematurely, and were not suitable for their intended use.
- 117. In failing to disclose the defects with the transmission, Defendant has knowingly and intentionally concealed material facts and breached its duty not to do so.

reasonably reliable and safe transportation because, inter alia, the Class Vehicles and their Clutch Systems suffered from an inherent defect at the time of sale and thereafter are not fit for their particular purpose of providing safe and reliable transportation.

- 131. Defendant impliedly warranted that the Class Vehicles were of merchantable quality and fit for such use. This implied warranty included, among other things: (i) a warranty that the Class Vehicles and their Clutch Systems were manufactured, supplied, distributed, and/or sold by FCA were safe and reliable for providing transportation; and (ii) a warranty that the Class Vehicles and their Clutch Systems would be fit for their intended use while the Class Vehicles were being operated.
- 132. Contrary to the applicable implied warranties, the Class Vehicles and their Clutch Systems at the time of sale and thereafter were not fit for their ordinary and intended purpose of providing Plaintiffs and Class Members with reliable, durable, and safe transportation. Instead, the Class Vehicles are defective, including the defective design and manufacture of their Clutch Systems.
- 133. The alleged Clutch Defect is inherent in each Class Vehicle and was present in each Class Vehicle at the time of sale.
- 134. As a result of Defendant's breach of the applicable implied warranties, owners and/or lessees of the Class Vehicles suffered an ascertainable loss of money, property, and/or value of their Class Vehicles. Additionally, as a result of the Clutch Defect, Plaintiffs and Class Members were harmed and suffered actual damages in that the Class Vehicles' clutch components are substantially certain to fail before their expected useful life has run.
- 135. Defendant's actions, as complained of herein, breached the implied warranty that the Class Vehicles were of merchantable quality and fit for such

use in violation of California Civil Code §§ 1792 and 1791.1.

FOURTH CAUSE OF ACTION

(Breach of Implied Warranty under the Magnuson-Moss Warranty Act, 15 U.S.C. § 2303 et seq.)

- 136. Plaintiffs incorporate by reference the allegations contained in the preceding paragraphs of this Complaint.
- 137. Plaintiffs bring this cause of action on behalf of themselves and on behalf of the Nationwide Class, or, in the alternative, on behalf of the California
- 138. The Class Vehicles are a "consumer product" within the meaning of the Magnuson-Moss Warranty Act, 15 U.S.C. § 2301(1).
- 139. Plaintiffs and Class Members are "consumers" within the meaning of the Magnuson-Moss Warranty Act, 15 U.S.C. § 2301(3).
- 140. Defendant is a "supplier" and "warrantor" within the meaning of the Magnuson-Moss Warranty Act, 15 U.S.C. § 2301(4)-(5).
- 141. FCA impliedly warranted that the Class Vehicles were of merchantable quality and fit for such use. This implied warranty included, among other things: (i) a warranty that the Class Vehicles and their Clutch Systems were manufactured, supplied, distributed, and/or sold by FCA were safe and reliable for providing transportation; and (ii) a warranty that the Class Vehicles and their Clutch Systems would be fit for their intended use while the
- 142. Contrary to the applicable implied warranties, the Class Vehicles and their Clutch Systems at the time of sale and thereafter were not fit for their ordinary and intended purpose of providing Plaintiffs and Class Members with reliable, durable, and safe transportation. Instead, the Class Vehicles are defective, including but not limited to the defective design of their Clutch

1	produced at trial; and			
2	(l) Such other relief as may be appropriate under the			
3	circumstances.			
4	DEMAND FOR JURY TRIAL			
5	155. Pursuant to Federal Rule of Civil Procedure 38(b) and Southern			
6	District of California Local Rule 38.1, Plaintiffs demand a trial by jury of any			
7	and all issues in this action so triable.			
8	Details Issue 10, 2017			
9	Dated: June 19, 2017 Respectfully submitted,			
10	Capstone Law APC			
11				
12	By: <u>/s/ Jordan L. Lurie</u> Jordan L. Lurie			
13	Tarek H. Zohdy Cody R. Padgett Karen L. Wallace			
14	Karen L. Wallace			
15	Attorneys for Plaintiffs Carlos Victorino and Adam Tavitian			
16				
17				
18				
19				
20				
21				
22				
23				
24				
25				
26				
27				
28				
	Page 49			

FIRST AMENDED CLASS ACTION COMPLAINT

EXHIBIT 1

1 2 3 4 5 6 7 8	Jordan L. Lurie (SBN 130013) Jordan.Lurie@capstonelawyers.com Robert Friedl (SBN 134947) Robert.Friedl@capstonelawyers.com Tarek H. Zohdy (SBN 247775) Tarek.Zohdy@capstonelawyers.com Cody R. Padgett (SBN 275553) Cody.Padgett@capstonelawyers.com Karen L. Wallace (SBN 272309) Karen.Wallace@capstonelawyers.com Capstone Law APC 1840 Century Park East, Suite 450 Los Angeles, California 90067 Telephone: (310) 556-4811 Facsimile: (310) 943-0396				
9 10	Attorneys for Plaintiffs Carlos Victorino and Adam Tavitian				
11	UNITED STATES DISTRICT COURT				
12	SOUTHERN DISTRICT OF CALIFORNIA				
13			1400\4047.0D0 D		
14	CARLOS VICTORINO and ADAM TAVITIAN, individually, and on	Case No.:	'16CV1617 GPC JLB		
15	behalf of other members of the general public similarly situated,	DECLARATION OF CARLOS			
16	Plaintiffs,	VENUE F	NO IN SUPPORT OF OR CLASS ACTION		
17	V.	CIVIL CO	INT PURSUANT TO DE SECTION 1780(d)		
18	FCA US LLC, a Delaware limited				
19	liability company, Defendant.				
20	Defendant.				
21					
22					
23					
24					
25					
26					
27					
28					

DECL, OF CARLOS VICTORINO IN SUPPORT OF PLAINTIFF'S SELECTION OF VENUE FOR TRIAL

DECLARATION OF CARLOS VICTORINO

I, Carlos Victorino, declare under penalty of perjury as follows:

- 1. I make this declaration based upon my personal knowledge except as to those matters stated herein that are based upon information and belief, and as to those matters I believe them to be true. I am over the age of eighteen, a citizen of the State of California, and a Plaintiff in this action.
- 2. Pursuant to California Civil Code section 1780(d), this Declaration is submitted in support of Plaintiff's Selection of Venue for the Trial of Plaintiffs' Cause of Action alleging violation of California's Consumers Legal Remedies Act.
- 3. I reside in Chula Vista, California, which is in the County of San Diego. I keep my vehicle, which is the subject of this lawsuit, at my home in Chula Vista. I also service my vehicle in the County of San Diego.
- 4. I am informed and believe that Defendant FCA US LLC ("Defendant") is a Delaware limited liability company, organized and existing under the laws of the State of Delaware, and registered to conduct business in California. Defendant FCA US LLC's Corporate Headquarters are located at 1000 Chrysler Drive, Auburn Hills, Michigan 48326. On information and belief, Defendant conducts business in San Diego County, including marketing, distributing, selling, and servicing vehicles through its authorized dealerships.

//

- 5. Based on the facts set forth herein, this Court is a proper venue for the prosecution of Plaintiffs' Cause of Action alleging violation of California's Consumers Legal Remedies Act because vehicles that are the subject of this lawsuit are situated here, and a substantial portion of the events giving rise to my claims occurred here. Further, Defendant conducts business in the Southern District of California and the County of San Diego, California, including, but not limited to, marketing, distributing, selling, and/or servicing Class Vehicles to Class Members.
- 6. I declare under penalty of perjury under the laws of California and the United States of America that the foregoing is true and correct.

Executed on June 24____, 2016 in Chula Vista, California.



1 PROOF OF SERVICE 2 I am employed in the State of California, County of Los Angeles. I am 3 over the age of 18 and not a party to the within suit; my business address is 1875 Century Park East, Suite 1000, Los Angeles, California 90067. 4 On June 19, 2017, I served the document described as: FIRST AMENDED CLASS ACTION COMPLAINT on the interested parties in this action by sending on the interested parties in this action by sending [] the original [or] [✓] a true copy thereof [✓] to interested parties as follows [or] [] as stated on the attached 5 6 service list: 7 PLEASE SEE ATTACHED SERVICE LIST 8 **BY MAIL** (ENCLOSED IN A SEALED ENVELOPE): I deposited the envelope(s) for mailing in the ordinary course of business at Los Angeles, California. I am "readily familiar" with this firm's practice of 9 collection and processing correspondence for mailing. Under that practice, sealed envelopes are deposited with the U.S. Postal Service 10 that same day in the ordinary course of business with postage thereon fully prepaid at Los Angeles, California. 11 **BY E-MAIL**: I hereby certify that this document was served from Los 12 Angeles, California, by e-mail delivery on the parties listed herein at their most recent known e-mail address or e-mail of record in this 13 |X|**VIA CM/ECF**: I hereby certify that this document was served via the 14 USDC CM/ECF on the parties Notice of this filing was served by email to all parties by operation of the Court's electronic filing system or 15 by mail to anyone unable to accept electronic filing as indicated on the Notice of Electronic Filing. I certify that the parties or their counsel are 16 registered as ECF filers and that they will be served by the CM/ECF system. 17 **BY PERSONAL SERVICE**: I caused to be delivered by messenger such envelope(s) by hand to the office of the addressee(s). **BY OVERNIGHT DELIVERY**: I am "readily familiar" with this 18 firm's practice of collection and processing correspondence for 19 overnight delivery. Under that practice, overnight packages are enclosed in a sealed envelope with a packing slip attached thereto fully prepaid. The packages are picked up by the carrier at our offices or 20 delivered by our office to a designated collection site. 21 |X|(**FEDERAL**) I declare that I am employed in the office of a member of the bar of this court at whose direction the service was made. 22 (STATE) I declare under penalty of perjury under the laws of the State of California that the foregoing is true and correct 23 24 Executed this 19th day of June, 2017 at Los Angeles, California. Pound Pormstam 25 26 Pouneh Porooshani 27

28

SERVICE LIST

/.	

William M Low

KathyA. Wisniewski Stephen A. D'Aunoy THOMPSON COBURN LLP One US Bank Plaza

Edwin Boniske
HIGGS FLETCHER & MACK LLP
401 West "A" Street, Suite 2600
San Diego, CA 92101-7913
wlow@higgslaw.com

kwisniewski@thompsoncoburn.com sdaunoy@thompsoncoburn.com

St. Louis, Missouri 63101